

REF #	DATE & TIME	NAME (LAST, FIRST)	PH#	COMPLAINT TYPE	LOCATION	COMPLAINT	FM O&G ACTION	CALLER RESPONSE	RESPONSE TIME	CSD REPORTING (EMAIL)	DATE & TIME REPORTED	COMMENTS
1316	07/29/16 1000	AQMD Inspector	1.800.288.7664	Odor	Baldwin Hills	<p>FM O&amp;G was contacted by an AQMD inspector regarding odor complaints called into their 800 number. AQMD received an odor complaint on Friday (7/22) at 12:57 a.m. from a Baldwin Hills resident located directly north of the field and east of La Cienega. The resident described the odor as burnt rubber.</p> <p>SCAQMD also received five (5) complaint on Monday (7/25) between 8:23 p.m. – 9:23 p.m. all from Baldwin Hill s residents, also located north of the field and east of La Cienega.</p> <p>Three (3) of the residents described the odor as burnt rubber, one (1) a chemical odor, and one (1) a skunk odor.</p> <p>(pg)</p>	<p>FM O&amp;G Operations verified there were no issues on the field and there were no alarms from the air monitoring equipment.</p> <p>Met Station data showed the wind direction during the time in question was from the NE towards the SW. Based on the wind direction, blowing towards the field, the odor could not have originated from the FM O&amp;G field.</p>	N/A	N/A	<p>DRP: (tstapleton)</p> <p>AQMD: (mhernandez)</p>	<p>07/29/16 1106</p> <p>07/29/16 1106</p>	No drilling has occurred onsite in two years.

1416	09/27/16 0910	AQMD Inspector	1.800.288.7664	Odor	Baldwin Hills	<p>An AQMD inspector contacted FM O&amp;G regarding five odor complaints called into their 800 number on Friday (9/23).</p> <p>The residents located directly north of the field indicated the odors occurred between 9:00 pm - 10:00 pm. According to the inspector, the odor described by the residents was a foul or burning odor.</p> <p>The inspector responded to the site of the complaints at 11:00 pm and detected no odors. (pg)</p>	<p>FM O&amp;G Operations verified there were no issues in the field and there were no alarms from the air monitoring equipment.</p> <p>Met Station data showed the wind direction during the time in question was from the NE towards the SW.</p> <p>Based on the wind direction, blowing towards the field, the odors could not have originated from the FM O&amp;G operations.</p>	N/A	N/A	<p>DRP: (tstapleton)</p> <p>AQMD: (mhernandez)</p>	<p>09/27/16 1005</p> <p>09/27/16 1005</p>	No drilling has occurred onsite in two years.