



**COMMUNITY STANDARDS DISTRICT – COMPLAINT LOG
SECOND QUARTER 2024**

Q2-24-01: On 05/10/2024 @ 10:51 AM, Sentinel Peak received a telephone call from a SCAQMD inspector who conveyed they had received a complaint of dust near the intersection of Stocker Road and S. Fairfax Avenue from Sentinel's main driveway. The inspector also mentioned noticing some visible track-out at this location.

Reference #	Date & Time	Reporting Party (R/P) Name (Last, First)	Phone #	Location	Complaint	CSD Reporting (EMAIL - Date/Time)
Q2-24-01	5/10/2024 @ 10:51 AM	Tavasolian, Adam SCAQMD Inspector	[REDACTED]	Stocker Rd and S. Fairfax Ave	Dust	Delatorre Email - 5/28/2024 @ 11:53 AM
Comments/ Sentinel Peak Resources actions:	<ul style="list-style-type: none"> ● Complaint: At 10:51 AM, Joe Walters of Sentinel Peak received a telephone call from an SCAQMD Inspector who reported receiving a complaint of dust near the intersection of Stocker Road and S Fairfax Avenue. The inspector noticed some visible track-out at this location from Sentinel's North driveway. ● SPR Response: At 10:54 AM, Joe Walters immediately notified our Operations site leads to address the issue. ● SPR Operator Assessment: At 10:54 AM, Sentinel's Operation leads were contacted and provided the location of the dust complaint. At 11:21 AM, a Sentinel crew was deployed to dry sweep the driveway and offsite extents. At 12:51 PM, Sentinel Operations confirmed cleanup of the area. At 6 AM on 5/11/24, mitigation measures were addressed with Operations staff to properly maintain dust and track-out from this area. ● SCAQMD Assessment: At 2:10 PM, a picture of the clean driveway area was sent to the AQMD Inspector. At 3:02 PM, the AQMD Inspector provided a positive response to the clean up. ● On-site MET Station: Hourly wind direction and wind speed are provided from 9 AM to 1 PM on 5/10/24 via the Sentinel MET Station. Average wind direction and speed throughout this timeframe was from the west southwest (WSW, 245°) and blowing to the east-northeast (ENE) at 9.2 mph. ● Conclusion: Based on our findings including wind direction and location of the complaint, the road dust was from Sentinel operations and immediate action was taken to clean up and mitigate future track-out. 					

Complaint Reference #

Q2-24-01

Data was saved using Vista Data Vision

Saved: 2024-05-28 17:53:50

Time Period: 2024-05-10 00:00:00 - 2024-05-11 00:00:00

Summary Time Period: Hour

Time	WD_Vector [°]	WS_Vector [mph]	WD [General]
5/10/2024 9:00	250	5.8	WSW
5/10/2024 10:00	237	7.8	WSW
5/10/2024 11:00	243	9.1	WSW
5/10/2024 12:00	247	10.7	WSW
5/10/2024 13:00	247	12.8	WSW
AVERAGE	245	9.2	WSW

